## **Inspection Report: Life Vests**

## S/N: 6-00-344-1761, 6-00-748-1761, 6-00-753-1761, 10-01-2163-176112-01-2340-1761, 12-01-2341-1761

Bryan Fabbri Science Systems and Applications, Inc. Hampton, Virginia

## Summary

Inspection date: 2013 Aug 28

Next Calibration date: 2015 Aug

A collection, analysis and reinspection of 7 Switlik Life Vests have been completed. Flightpath Services, Inc., performed the calibration. This inspection was completed on 2013 August 28.

Manufacturer: Switlik Serial Number: 6-00-344-1761, 6-00-748-1761, 6-00-753-1761, 10-01-2163-1761,12-01-2340-1761, 12-01-2341-1761

The inspection presented in data table format show that 6 vests were accepted and 1 was rejected. The 1 rejected had S/N: 90-186. This vest will no longer be used. The 6 lifevests accepted and passed inspection are good for 2 years from the inspection date.

The following pages provide more detail of the inspection reports, including inspection of the CO2 cylinders among other checks.

Application: These vests are now up to date and can be worn as normal on helicopter flights to Chesapeake Light.

PHONE (201) 489-7950	FLIGHTPATH 500 HOLLISTER RD,	TETERBORO N.J. (	, INC.			
(201) 489-7950	REPAIR STA	ATION JG1R243K			FAX (2	01) 489-8537
0	LIFE VEST/FLOTATION D	EVICE INSPECTIO	N FORM			FORM 650
CUSTOMER BRIDAK	Fabboi		WORK O	RDER	RY71	735
YPE OF REPAIR: PERIODIC INSPEC	TION OTHER (H	TYPI AIND			8	77 17
EMARKS Ong Tube Tonn +	hom Vest 518.	hallenies s	· volley	DATE .	fill come	2510 17
EINSPECTION DUE	8-3	3015		900 11	c cmm	REC 27
REFER TO MFG. MAINTENAM	NCE MANUALS FOR DETAIL	ED INSTRUCTION	S FOR FACE	LINIT		
TSO MFG. MFG. PART NUMBER	SERIAL NUMBER VE				4	
1305 ALLAN S- TRAL	ACP	REJ #1 #2	BATTERY 1		EA WHISTLE YE	MIRROR
13DE TICK 600 5-7200-1	620-753-1761 02	+ ULOR	REI	22		
13DSVITCH 600 8-7200-1	6-00-344-1761 cg	04 19	di la	15		
131 5 (14 12-01 5-72 00-1	6-00-148-176( Oh	02 04	RJ 1	CT_		
130 Sull 12-01 5- 7200-11	12-01-2341-1761 02 12-01-2340-1761 02	02 04	Rg-1	20-	_	
13D Tuille 11-88 5-7200-2	90-186	Veces	100 1	-0		
				0		
DED INSPECTIONS	MECH. INSP.					
ECK INFLATION PIN FOR TRAVEL SERT AND TORQUE CO2 CYLINDER FETY INFLATION LEVER	the mil	TEMPERATUR TEMPERATUR		3 B	ARO IN 29	38
CK TO MFG. SPECIFICATIONS	The son I	The appliance identifi regulations of the Fede	ed above was repaire eral Aviation Admini	d and inspected is stration and is a	in accordance with curre	ent vice.
DRK COMPLETED AMARK	man.		PECTED	1 120	lly	
TE DATOS				2013		

	oving National Aviation Authority/Country: JNITED STATES	2. AUTHORIZED RELEA FAA FORM 8130-3, AIRWORTH	SE CERT	ROVAL TAG	3. Form Tracking Number SEE BLOCK 5	
	ganization Name and Addre		TEBBORO	N L 07508	5. Work Order, Contract, Number: R470	
FLIC	GHTPATH SERVICES,	INC., 500 HOLLISTER RD., TE	Eligibility:*	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
. tiem:		8. Part Number: 9.	Engineny.	To contract.		
1	LIFE PRESEVER	S-7200-11 N	A	5	SEE BLOCK 13	OVERHAULED
	AN FABBRI					
	3-00-753-1761, 6-00-3	44-1761, 6-00-748-1761, 12-0	F		CTION DUE 8-20	15 that work the
	3-00-753-1761, 6-00-3	44-1761, 6-00-748-1761, 12-0 at the work specifiedn block 12/13 war release to service under EASA Appro	F		CTION DUE 8-20	15 that work the
Flightpa compon	8-00-753-1761, 6-00-3 ath Services, Inc. certifies th tent is considered ready for Stage the items identified above	at the work specifiedn block 12/13 was release to service under EASA Appro were manufactured in conformity to: in a condition for safe operation.	s carried out in val Number: "I 19. 2 14 Certifies ti 12 and de Code of F approved	REINSPEC accordance with EASA, 145.6051. CFR 43.9 Return hat unloss otherwiseribed in Block for return to servi-	TION DUE 8-20 EASA-145 and in respect to the n to Service Other regulation data specified in Block 13, the r 13 was accomplished in aco res, part 43 and in respect to 1 (00)	that work the on specified in Block 13 work identified in Block cordance with Title 14, that work, the items are
Flightpa component 14. Celt Appr Non	th Services, Inc. certifies the nent is considered ready for	at the work specifiedn block 12/13 was release to service under EASA Appro were manufactured in conformity to: in a condition for safe operation.	s carried out in val Number: "I 19. 2 14 Certifics II 12 and di Code of F approved	CFR 43.9 Return hal unloss otherw socioted in Block	CTION DUE 8-20 EASA-145 and in respect to 1 In to Service () Other regulation deso specified in Block 13, the rs, part 43 and in respect to 1 too. 21. Ag CR	that work the on specified in Block 13 work identified in Block continuos with Title 14.

A	oving National Aviation Authority/Country: JNITED STATES	2. AUTHORIZED RELI FAA FORM 8130-3, AIRWO			3. Form Tracking Number SEE BLOCK 5	
	anization Name and Addre HTPATH SERVICES,	ss. CRS JG1R243K INC., 500 HOLLISTER RD.,	TETERBORO	N.J. 07608	5. Work Order, Contract, Number: R4703	
5, Item:	7. Description:	8. Part Number:	9. Eligibility:*	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	LIFE PRESEVER	S-7200-11	N/A	5	SEE BLOCK 13	OVERHAULED
BRY	AN FABBRI			51	VITLIK CMM 25-60-171	THE V MIT
6-	00-753-1761, 6-00-34	4-1761, 6-00-748-1761, 12 the work specifiedn block 12/13 v	F	1, 12-01-2340	1761	5
Flightpath component	00-753-1761, 6-00-34 Services, Inc. certifies than It is considered ready for r	the work specifiedn block 12/13 v elease to service under EASA App are manufactured in conformity to: a condition for safe operation.	Ras carried out in roval Number: "E 19. 2 14 Certifies th 12 and de Code of Fe	REINSPEC	TION DUE 8-201 EASA-145 and in respect to the to Service Context regulation as specified in Block 13, the w 13 was accomplished in accord	5 at work the a specified in Block 13 rock identified in Block
6-1 Flightpath component 14. Cettak Approv	00-753-1761, 6-00-34 Services, Inc. certifies than It is considered ready for r the items identified above w ved desting data and are in	the work specifiedn block 12/13 v elease to service under EASA App are manufactured in conformity to: a condition for safe operation.	nas carried out in roval Number: "E 19. 2 14 ( Certifies th 12 and dee Code of Fe approved fo	1, 12-01-2340- REINSPEC accordance with ASA.145.8051. CFR 43.9 Return 1 at unless otherwis sofibed in Block	TION DUE 8-201 EASA-145 and in respect to the to Service [] Other regulation as specified in Block 13, the w specified in Block 13, the w and 43 and in respect to the 21. App	5 at work the a specified in Block 13 rock identified in Block

A	oving National Aviation withority/Country: JNITED STATES	2. AUTHORIZED RELE FAA FORM 8130-3, AIRWOO	ASE CER	TIFICATE ROVAL TAG	3. Form Tracking Number SEE BLOCK 5	
	anization Name and Addres	ss. CRS JG1R243K INC., 500 HOLLISTER RD.,	FTERBORO	N I 07608	5. Work Order, Contract, Number: R470	
6. item:		8. Part Number:	9. Eligibility.*	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	LIFE PRESEVER		N/A	5	SEE BLOCK 13	OVERHAULED
13. REN BRY	ARKS AN FABBRI			S	WITLIK CMM 25-60-171	REV 27
6-	00-753-1761, 6-00-34	4-1761, 6-00-748-1761, 12-				15
Flaktnati	h Sanvicas. Inc. cartifies thatis	4-1761, 6-00-748-1761, 12- t the work specifiedn block 12/13 v elease to service under EASA App	F as carried out in		TION DUE 8-20	
Flightpati	h Services, Inc. certifies that Int is considered ready for re	the work specified  block 12/13 v	F as carried out in oval Number: "t	REINSPEC accordance with EASA .145.6051.	TION DUE 8-20	hat work the
Flightpati compone	h Services, Inc. certifies that int is considered ready for re age the items identified above we wed design data and are in	t the work specifiedn block 12/13 v elease to service under EASA App ere manufactured in conformity to: a condition for safe operation.	es carried out in oval Number: "t 19. 14 Certifies th	CFR 43.9 Return and unless otherwite	EASA-145 and in respect to the EASA-145 and in respect to the to Service the regulation are specified in Block 13, the to a specified in Block 13, the to a specified in a constraint of the top of top of the top of the top of top of the top of	hat work the in specified in Block 1 work identified in Bloc ordance with Title 14
Flightpati compone	h Services, Inc. certifies that ent is considered ready for re	t the work specifiedn block 12/13 v elease to service under EASA App ere manufactured in conformity to: a condition for safe operation.	es carried out in roval Number: "E 19. 14 Certifics th 12 and de Code of Fi	CFR 43.9 Return and unless otherwite	TION DUE 8-20 EASA-145 and in respect to the to Service Cother regulations as specified in Block 13, the 13 was accomplished in account s, part 43 and in respect to the second s	n specified in Block 1: work identified in Bloc cordance with Title 14 net work, the items ar
Flightpatt compone 14. Cerbs Appro	h Services, Inc. certifies that int is considered ready for re age the items identified above we wed design data and are in	t the work specifiedn block 12/13 v elease to service under EASA App ere manufactured in conformity to: a condition for safe operation.	F as carried out in oval Number: 1 19. 14 Certifies th 12 and de Code of F approved x: 20. Auto	CFR 43.9 Return tat unless otherwin seribed in Block	ETION DUE 8-20 EASA-145 and in respect to the to Service Other regulation are specified in Block 13, the 13 was accomplished in acc s, part 43 and in respect to the 20 21. Ap CRS	hat work the in specified in Block 1 work identified in Bloc ordance with Title 14

FAA/L	Authority/Country:	and a stand stand stand	EASE CER	TIFICATE ROVAL TAG	3. Form Tracking Number. SEE BLOCK 5		
4. 'Org	panization Name and Add	ress. CRS JG1R243K					
		, INC., 500 HOLLISTER RD.	TETERRORO	N.L. offices	5. Work Order, Contract, or Invoice Number;		
6. Item;	<ol><li>Description:</li></ol>	8. Part Number:	9. Eligibility."	N.J. 07608	R470		
			o. Lighting,	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1 13. REM	LIFE PRESEVER	S-7200-11	N/A	5	SEE BLOCK 13	OVERHAULED	
				SV	/ITLIK CMM 25-60-171	REV 27	
ohtoath :	Services Inc. continue to	44-1761, 6-00-748-1761, 12 I the work specifiedn block 12/13 v elease to service under EASA App	R	1, 12-01-2340-			
Flightpath : component 14. Certrice Approve	Services, Inc. certifies that I is considered ready for r the items identified above w of dostign data and are in proved design data-specif	t the work specifiedn block 12/13 v elease to service under EASA App ere manufactured in conformity to: a condition for safe operation. led in Block 13	R was carried out in: roval Number: "E 19. 14 C Certifies tha 12 and des Code of Fed approved for approved for	EINSPECT	1761	5 I work the specified in Block 13 rk identified in Block	
Flightpath : component 4. Cethles Approve Non-app 5. Author	Services, Inc. certifies that I is considered ready for r Be items identified above w of detage, data and are in	If the work specifiedn block 12/13 v elease to service under EASA App ere manufactured in conformity to: a condition for safe operation.	R was carried out in: roval Number: "E 19. 14 C Certifies that 12 and des Code of es approved for	I, 12-01-2340- EINSPECT locordance with E SA.145.6051. FR 43.9 Return to unless otherwise ribed in Block 13 and Restudations	Service Cother regulation of the specified in Block 13, the way was accomplished in accorrect to that 13 and in respect to that 121. Approx	5 I work the specified in Block 13 rk identified in Block	

FAAA	Authority/Country:	AUTHORIZED REL FAA FORM \$130-3, AIRW	EASE CER	TIFICATE PROVAL TAG	3. Form Tracking Number SEE BLOCK	
4. 'Org	ganization Name and Addre	ss. CRS JG1R243K				
FLIC	OHTPATH SERVICES,	INC., 500 HOLLISTER RD.	TETERBORO	N I 07608	5. Work Order, Contract Number:	
6. flem:	<ol><li>Description:</li></ol>	8. Part Number:	9. Eligibility:*	10. Quantity:	R470 11. Serial/Batch Number:	
1	LIFE PRESEVER	S-7200-11	N/A	5	SEE BLOCK 13	12. Status/Work: OVERHAULED
				SV	VITLIK CMM 25-60-171	REV 27
ightoath	Services Inc. certifics that	4-1761, 6-00-748-1761, 12	R	1, 12-01-2340- EINSPEC	1761	
lightpath	Services, Inc. certifies that It is considered ready for rel	the work specifiedn block 12/13 v ease to service under EASA App	R vas carried out in roval Number: "E/	EINSPEC accordance with E ASA .145.6051.	1761 TION DUE 8-201 FASA-146 and in respect to the	5 at work the
Tightpath componen 4. Centrage 3 Approv 3 Non-ap	Services, Inc. certifies that in the considered ready for relations identified above were dobbye, data and are in a sproved design data-specifie	the work specifiedn block 12/13 v ease to service under EASA App e manufactured in conformity to: condition for safe operation.	Reas carried out in . roval Number: "Ev 19. 14 C Certifies that 12 and dess Code of Fed	EINSPEC accordance with E ASA .145.6051.	1761	5 at work the specified in Block 13 ark identified in Block
ightpath amponen 4. Cethler ] Approv ] Non-ap 5. Author	Services, Inc. certifies that in the considered ready for relations identified above were ded destign data and are in a	the work specifiedn block 12/13 v ease to service under EASA App e manufactured in conformity to: condition for safe operation.	R was carried out in roval Number: "E 19. 14 C Certifies tha 12 and des Code of Fed approved for	EINSPEC accordance with E ASA.145.6051. FR 43.9 Return to t unless otherwise rilbed in Block 10.	1761 TION DUE 8-201 ASA-145 and in respect to the service Other regulation a specified in Block 13, the we a was accomplished in accor part 43 and in respect to that 12. Appendix	5 at work the specified in Block 13 ark identified in Block

	roving National Aviation Authority/Country: JNITED STATES	2. AUTHORIZED REL FAA FORM 8130-3, AIRWO			3. Form Tracking SEE BL		
FLIC	panization Name and Addre GHTPATH SERVICES,	ss. CRS JG1R243K INC., 500 HOLLISTER RD.,	TETERBORO,	N.J. 07608	5. Work Order, C Number:	R470	
6. llem:	7. Description:	8. Part Number:	9. Eligibility:*	10. Quantity:	11. Serial/Batch N	mber:	12. Status/Work:
1	LIFE PRESEVER	S-7200-12	N/A	1	10-01-2163-1	761	OVERHAULED
Fäghtpath	s Services, inc. certifies that It is considered ready for re	the work specifiedn block 12/13 v lease to service under EASA App	as carried out in a	accordance with F	TION DUE 8 ASA-145 and in resp	-201 ect to th	5 at work the
Componen	ni is considered ready for re	lease to service under EASA App	vas carried out in a roval Number: "E/	accordance with E ASA .145.6051.	ASA-145 and in resp	ect to th	at work the
14. Catter	es the items identified above we	rease to service under EASA App remanufactured in conformity to: a condition for safe operation.	19. D14 C Certifies tha 12 and dess Code of Fed	FR 43.9 Return to tuniess otherwise cribed in Block 1	ASA-145 and in resp o Service Other re e specified in Block 1: 3 was accomplished , part 43 and in resp	gulation	at work the specified in Block 13 ork identified in Block rdance with Title 14
14. Cansie Approv Non-ap 15. Autho	es the items identified above we wed deidige data and are in a	rease to service under EASA App remanufactured in conformity to: a condition for safe operation.	19. D14 C Certifies that 2 and desc Code of Fec approved for	ER 43.9 Return to tuniess otherwise cribed in Block 1 derail Regulations.	ASA-145 and in resp o Service Other re e specified in Block 1: 3 was accomplished , part 43 and in resp	gulation 3, the w in accord ct to the	at work the specified in Block 13 ork identified in Block rdance with Title 14